

# VERSION REPORT

PRODUCT:

DDS VERSION V10.03

01/07/2024

## CONTENTS

1	Checksum DDS V10.03.....	2
2	Manuals.....	2
3	Product stop .....	2
4	Incompatibilities.....	2
4.1	Hardware.....	2
4.2	Software .....	2
5	Hardware modifications .....	2
6	New features .....	2
7	Modifications .....	2

---

## 1 CHECKSUM DDS V10.03

---

Localization	Identifier
\\fas\Soft_interno\Reg\DDS-SETUP+LOAD-DDS\V-estándar\V1003WIN.exe	4933

---

## 2 MANUALS

---

No manuals affected.

---

## 3 PRODUCT STOP

---

It does not correspond to any product stop.

---

## 4 INCOMPATIBILITIES

---

### 4.1 HARDWARE

This version can only be loaded on AXD vecon5 boards.

It will not be valid for MAB or VERCUS, since the necessary Hw will not be developed.

It will only work on boards with 6 MHz oscillator for the C165 and PLL activated with a 4.5 gain.

### 4.2 SOFTWARE

Winddsetup: Revision V1001\_230530 boot or newer is required.

---

## 5 HARDWARE MODIFICATIONS

---

New vecon5 hardware.

---

## 6 NEW FEATURES

---

None.

---

## 7 MODIFICATIONS

---

None.

---

## CORRECTED ERRORS

---

1. [AXD SPD-415](#)

Error 215 does not reset from CNC.

2. [AXD SPD-409](#)

Windds: strange effect of the version loading progress bar.